





- 1090921 J - 4050917
- * 1090932 J - 4050918
- ▲ 4050928 J




Réf : 0401611

F40

30-66



1 F40 → * [15 Vaches laitières - Dairy cows - Milchkühe
20 Bovins - Cattle - Rinder]



N° 4690405 - 02/2016

Branchement - Connection - Anschluss

The diagram illustrates the three steps for connecting the water meter to the wall:

- 1** The meter is positioned against the wall, and the connection pipes are aligned.
- 2** The meter is secured to the wall using a bracket and screws.
- 3** The meter is fully installed. A warning symbol indicates that the meter should not be painted over.

Montage - Installation

The diagram illustrates the installation of a sensor probe in two steps:

- (a)** The probe is inserted into the mounting plate. A bracket is shown being positioned around the probe.
- (b)** The bracket is secured to the mounting plate with a screw, and the probe is inserted into the bracket.

KIT A369
Pour
Für
For

PROFLOW
Ø 3/4" (25 PE)

KIT A331

Ø 4

02
)

I 220 $\triangleright$ I 300

Vis de réglage
Regulating screw
Regulierschraube

Ferme
Off
Zu



Pression maxi
Maxi pressure
Maxi Wasserdruck

6 Kg/cm²
87.06 lbs/□"